



MC18 R5/6k Central Right Hand Crankshaft Web with the 25mm diameter big end pin removed and a 22mm hole made in its place. This gives a minimum distance between the 2 holes of 2.25mm. So it is quite probable that the web will crack here when the pins are pressed in. However, a 25mm big end hole would be worse at 0.75mm