



5.0(1) ROOF FRAMING (Picture
1) Hole in frame member



5.0(2) ROOF FRAMING (Picture
1) Damaged framing