

- Year to Date: (45 K3Es Completed)
  - **Environmental Improvement: 1**
  - **Service Improvement: 4**
  - **Efficiency Improvement: 21**
  - **Quality Improvement: 9**
  - **Inventory Improvement: 4**
  - **Safety Improvement: 22**
  - **5S Improvement: 9**

## Pictured to the right:

The tools for the coil winding lathe were not well organized. This required the operator of the machine to find the tools prior to proceeding on a job. A shadow board was created to hold, identify, and organize the required tools for the coil winding lathe.

