

Safety K3E March Highlight

Pictured to the right:

The Assembler was required to use her hand as a fixture in order to hold the “T” and stamp the part. A chisel holder was purchased to hold the “T” stamp, removing the hand from being potentially struck.



Before



After

Credit: Tehreen Bano

Pictured to the left:

The employee was required to bend down to secure the controller to the skid. Also, the mounting holes were located underneath the enclosure, which made them hard to reach and see.

Shipping brackets were fabricated to slide into the enclosure’s mounting legs. This holds the unit in place and mounting holes were moved to make it easier to install.



Credit: Cory Sullivan, Jonathan Ascensio, Mike Neam, Crystal McGee, Gethro Dormes