

- Year to Date: (22 K3Es Completed)
 - **Environmental Improvement: 0**
 - **Service Improvement: 1**
 - **Efficiency Improvement: 12**
 - **Quality Improvement: 5**
 - **Inventory Improvement: 2**
 - **Safety Improvement: 9**
 - **5S Improvement: 4**

Pictured to the right:

The legibility of the nameplate caused several issues when trying to ship the contactors. Among the issues were incorrect serial numbers and pulling the wrong part number. By utilizing a magnifying glass with a light on it the process was error proofed and efficiency improved.

