

K3E July Highlight

- Year to Date: (28 K3Es Completed)
 - **Environmental Improvement: 0**
 - **Service Improvement: 1**
 - **Efficiency Improvement: 14**
 - **Quality Improvement: 5**
 - **Inventory Improvement: 2**
 - **Safety Improvement: 15**
 - **5S Improvement: 5**

Pictured to the right:

The keypads on the Lean Lifts had sharp corners that you could bump into and cause injury. Ross placed a gasket around all corners of the keypads to cover up the sharp edges.

