

- Year to Date: (7 K3Es Completed)
  - **Environmental Improvement: 0**
  - **Service Improvement: 0**
  - **Efficiency Improvement: 5**
  - **Quality Improvement: 1**
  - **Inventory Improvement: 0**
  - **Safety Improvement: 4**
  - **5S Improvement: 0**

## Pictured to the right:

The table had sharp edges that could cause a cut injury. The edges were wrapped in foam to cover the sharp edges and eliminate the potential hazard.

